



**MINNEAPOLIS PUBLIC SCHOOLS
Environmental Health & Safety Division**

Lead in Water Safety Program

As a result of the water sampling performed between September 1998 and the present, the following Minneapolis Public School facilities have been identified as having lead levels above the action level. Each facility on this list performs water flushing to reduce lead levels. Sites on this list should be considered for domestic water replacement. Elementary schools should be the first priority or a location where domestic water piping is in poor condition and requires replacement.

High Lead in Water Facilities: Domestic Water Replacement

Facility	Comments
Andersen	Recommend domestic water replacement
Anthony	Recommend domestic water replacement
Anwatin	Recommend domestic water replacement
Armatage	Recommend domestic water replacement
Barton	New addition and NE wing are low lead. Original old building is high lead and domestic water replacement is recommended.
Bethune	Recommend domestic water replacement
Bryn Mawr	New building is low lead. Old church school building is high lead and domestic water replacement is recommended.
Dowling	Recommend domestic water replacement
Edison	Main building is low lead. High lead in west gym building and domestic water replacement is recommended.
Emerson	Recommend domestic water replacement
Ericsson(Northrup)	Recommend domestic water replacement
Field	Recommend domestic water replacement
Franklin	Recommend domestic water replacement
Hall	New addition is low lead. Original old building is high lead and domestic water replacement is recommended.
Henry	Main Building is low lead. High lead in North athletic building and domestic water replacement is recommended.
Hiawatha	Recommend domestic water replacement
Jefferson	Recommend domestic water replacement
Keewaydin	New addition is low lead. Original old building is high lead and domestic water replacement is recommended
Kenny	Recommend domestic water replacement
Kenwood	Recommend domestic water replacement
Lake Harriet Upper	Recommend domestic water replacement
Lyndale	Recommend domestic water replacement
North	Recommend domestic water replacement
North Star	Recommend domestic water replacement
Northeast	Recommend domestic water replacement
Olson	Recommend domestic water replacement
Ramsey	Recommend domestic water replacement
Roosevelt	Had a domestic water replacement in old building in 2002 but still tested high lead. Recommend further piping replacement.
Seward	New additions are low lead. High lead in old original building and domestic water replacement is recommended

Sheridan	Recommend domestic water replacement
Facility	Comments
South	Recommend domestic water replacement
Southwest	Recommend domestic water replacement
Tuttle	Had a domestic water replacement in 2002 but still had high lead. Recommend further piping replacement
Waite Park	Recommend domestic water replacement
Washburn	Recommend domestic water replacement
Wenonah	Recommend domestic water replacement
Windom	Recommend domestic water replacement
Wilder	Recommend domestic water replacement